

## Contents

1. Introduction.....	1
2. Field scanning records .....	2
2.1 Antakya city and Hatay Airport Road .....	3
2.1.1. Viaduct on D817 near Saraykent, Antakya city.....	3
2.1.2. Bridges over Orontes River in downtown Antakya city.....	7
2.1.3. Hatay Airport Road and Hatay Airport .....	14
2.2 Bridge collapse in the suburb of Nurdağı .....	18
2.3 Tarsus–Adana–Gaziantep motorway (O52) Viaduct between Bahçe and Kömürler toll booths .....	23
2.3.1. Başpınar Viaduct on Motorway O52.....	24
2.3.2. Turgut Özal Viaduct on Motorway O52 .....	27
2.3.3. Atatürk Viaduct on Motorway O52 .....	32
2.3.4. Nurdağı Viaduct on Motorway O52 .....	34
2.3.5. Şehitler Viaduct on Motorway O52 .....	39
2.3.6. Kızlaç Viaduct on Motorway O52 .....	43
2.3.7. Vecdi Diker Viaduct on Motorway O52 .....	50
2.4 Damage to earthworks, a tunnel, and bridges on national highways connecting Gaziantep and Malatya .....	53
2.4.1. Section along the Göksu River on D850 Malatya/Kahramanmaraş Highway .....	53
2.4.2. Erkenek Tunnel on D850 Malatya/Kahramanmaraş Highway .....	56
2.4.3. Beylerderesi Turgut Özal Viaduct on D850 Malatya/Kahramanmaraş Highway .....	61
2.4.4. Tohma Bridge on D875 Malatya/Keban Highway .....	70
2.5 Examples of other noteworthy observations .....	86
2.5.1. Roads in Downtown Antakya city .....	86
2.5.2. Suburban roads of Antakya city .....	87
2.5.3. D400 section near Sakcagoz between Gaziantep and Nurdağı .....	88
3. Summary and suggested research topics to update seismic design practice and the Japanese Specifications for Highway Bridges .....	90
References .....	93